

# Illinois Commerce Commission

## Pipeline Safety

### Pipeline Safety Report

**Inspection #: 2014-P-00422**

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Exit Meeting Contact: Charles Tebbe	Total Man Days: 3
Pipeline Safety Representative(s): Valerie Schwing	
Company Representative to Receive Report: Michael Fuller	<b>Emailed Date:</b>
Company Representative's Email Address: mfuller2@ameren.com	10/30/2014

#### Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Design Testing and Construction	Wood River, Waterloo	Valerie Schwing	Maryville	2	9/3/2014, 9/4/2014	Charles Tebbe
Standard Inspection - Field Audit	Caseyville	Valerie Schwing	Maryville	1	9/5/2014	Charles Tebbe

#### Statement of Activities

On September 3-4, 2014, a Construction Audit was conducted at Ameren Illinois, in Wood River and Waterloo, Illinois, to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590. On September 3, 2014 Staff witnessed the contracting crew Infrasource complete shoring and excavate around the existing Enable 24 inch 1982 steel pipe that has a MAOP of 400 PSI. Staff examined new prefabricated welds and pipe coating. On September 4, 2014, Staff witnessed the construction crew KS Energy in Waterloo conduct directional boring. The previous day a weld at the Waterloo job site had burned through and the Ameren Crew had to weld a pumpkin to fix the leak. While witnessing the directional boring Chuck Tebbe was able to help save valuable time by assisting with trouble shooting of a boring machine by pointing out a micro switch which was switched due to mud build up. The KS Energy crew could not complete the boring that day due to hitting hard rock. Staff went back to the Wood River work site in the afternoon to witness more shoring and excavating. On September 5, 2014, Staff witnessed an Ameren crew do an annual inspection of regulator station number CH038 in Caseyville. The Ameren crew consisted of two Journeymen, Ryan Curry and David Lingle.

#### Exit Statement

N/A

### **INSPECTION FINDINGS**

#### **Design Testing and Construction**

##### **Issues(s) Found:**

[NO ISSUES FOUND]

##### **Notice Of Amendment(s) Found:**

[NO NOAS FOUND]

##### **Notice Of Violation(s) Found:**

[NO NOPVS FOUND]

Illinois Commerce Commission

Pipeline Safety

Pipeline Safety Report

Inspection #: 2014-P-00422

Standard Inspection - Field Audit

**Issues(s) Found:**

[NO ISSUES FOUND]

**Notice Of Amendment(s) Found:**

[NO NOAS FOUND]

**Notice Of Violation(s) Found:**

[NO NOPVS FOUND]

**PAST INSPECTION FINDINGS**

**Issue(s) Corrected:**

[NO ISSUES CORRECTED]

**Notice Of Amendment(s) Corrected:**

[NO NOAS CORRECTED]

**Notice of Violations(s) Corrected:**

[NO NOPVS CORRECTED]